
CONTROL FOR ODDY 2016-2019

Si: diffuse lighting

Defective copper sourced from Fine Metals. Issue resolved in future by 2020 ordering unannealed copper. Test coupons scored with control coupons as





CONTROL FOR ODDY 2016-2019

GA: glancing angle light source

Defective copper sourced from Fine Metals. Issue resolved in future by 2020 ordering unannealed copper. Test coupons scored with control coupons as

